

## PIC16(L)F1782/1783 Family Silicon Errata and Data Sheet Clarification

The PIC16(L)F1782/1783 family devices that you have received conform functionally to the current Device Data Sheet (DS41579D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC16(L)F1782/1783 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**B4**).

Data Sheet clarifications and corrections start on page 10, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
  - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16(L)F1782/1783 silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	DEVICE ID<13:0> <sup>(1),(2)</sup>		
	DEV<8:0>	REV<4:0> Silicon Revision	
		B2	B4
PIC16F1782	01 0111 000	0 0110	0 1000
PIC16LF1782	01 0111 001	0 0110	0 1000
PIC16F1783	01 0110 010	0 0110	0 1000
PIC16LF1783	01 0111 010	0 0110	0 1000

- Note 1:** The Device ID is located in the configuration memory at address 8006h.
- 2:** Refer to the “PIC16(L)F178X Memory Programming Specification” (DS41457) for detailed information on Device and Revision IDs for your specific device.

# PIC16(L)F1782/1783

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>	
				B2	B4
ADC	Fosc/2	1.1	Fosc/2 not functional.	X	
ADC	Offset	1.2	Time between conversions affects offset.	X	
ADC	INL (12-bit mode)	1.3	INL is $\pm 4$ LSb.	X	
ADC	FRC	1.4	ADC not functional if using FRC with Fosc < 2 MHz.	X	
Op Amp	Offset	2.1	Offset increases when Common mode < 200 mV.	X	
Comparator	Low-Power mode	3.1	Improper Low-Power mode operation.	X	X
Comparator	Typical Offset Performance mode	3.2	Normal Speed mode.	X	
Data EEPROM	Endurance	4.1	Limited to 10k cycles, VDD < 2.3V, PIC16LF1782/1783.	X	
HF Internal Oscillator	Clock Switching	5.1	Clock switching can cause a single corrupted instruction.	X	
PSMC	Rising Edge Input	6.1	Period and falling edge race condition.	X	X
PSMC	Auto-shutdown	6.2	Failure to auto-restart after shutdown from comparator.	X	
Low-Dropout (LDO) Voltage Regulator	Low-Power Sleep	7.1	Unexpected Resets may occur at ambient temperatures below 0°C.	X	X
FVR	FVR Module	8.1	Use of FVR module can cause device to Reset.	X	X
PFM	PFM Self-Write	9.1	PFM self-write will not work depending on clock selection.		X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**B4**).

### 1. Module: ADC

#### 1.1 Operation with FOSC/2

The ADC is not functional when the ADCS<2:0> bits of ADCON1 select the Fosc/2 frequency.

##### Work around

Use the FRC selection which provides a valid TAD time, regardless of the system clock frequency.

##### Affected Silicon Revisions

B2	B4							
X								

#### 1.2 ADC Offset

The offset error exceeds the data sheet specification when the time between conversions is greater than 100 us.

##### Work around

The time dependent error is insignificant when the time between conversions is less than 100 us. When the time between conversions is greater than 100 us, take two back-to-back ADC conversions and discard the results of the first conversion.

##### Affected Silicon Revisions

B2	B4							
X								

# PIC16(L)F1782/1783

## 1.3 ADC INL (12-bit mode)

The ADC linearity is  $\pm 4$  LSB for the 12-bit mode. Below are typical INL graphs in 12-bit mode (See [Figure 1](#) and [Figure 2](#)).


### Work around

None.


### Affected Silicon Revisions

B2	B4						
X							

**FIGURE 1: ADC 12-BIT MODE, SINGLE-ENDED INL,  $V_{DD} = 3.0V$ ,  $T_{AD} = 4 \mu s$ ,  $25^{\circ}C$ , TYPICAL MEASURED VALUES**



**FIGURE 2: ADC 12-BIT MODE, SINGLE-ENDED INL,  $V_{DD} = 5.5V$ ,  $T_{AD} = 4 \mu s$ ,  $25^{\circ}C$ , TYPICAL MEASURED VALUES**



## 1.4 Incorrect Readings if using Fosc < 2 MHz

The ADC is not functional if using FRC with Fosc frequencies less than 2 MHz.

### Work around

Use frequencies greater than 2 MHz for correct ADC functionality.

### Affected Silicon Revisions

B2	B4						
X							

## 2. Module: Op Amp

### 2.1 Offset at Low Common Mode

The op amp offset at Common mode input voltages below 200 mV increases with respect to temperature. Below are typical graphs showing the increase in offset (See [Figure 3](#), [Figure 4](#) and [Figure 5](#)).


### Work around

None.

### Affected Silicon Revisions


B2	B4						
X							

**FIGURE 3: OP AMP TYPICAL OFFSET VOLTAGE AT 25°C, HIGH GBWP MODE (OPAxSP = 1), VDD = 3.6V, 0V ≤ CMV ≤ 5.5V**




# PIC16(L)F1782/1783

**FIGURE 4: OP AMP TYPICAL OFFSET VOLTAGE AT LOW VCM, 85°C,  
HIGH GBWP MODE (OPAxSP = 1), V<sub>DD</sub> = 3.6V, 0V ≤ CMV ≤ 0.5V**



**FIGURE 5: OP AMP TYPICAL OFFSET VOLTAGE AT 85°C,  
HIGH GBWP MODE (OPAxSP = 1), V<sub>DD</sub> = 3.6V, 0.5V ≤ CMV ≤ 3.5V**



### 3. Module: Comparator

#### 3.1 No Low-Power, No Low-Speed Mode

The comparator operation in Low-Power, Low-Speed mode (CxSP = 0) may not perform properly.

##### Work around

Use the comparator in High Power mode.

##### Affected Silicon Revisions

B2	B4						
X	X						

#### 3.2 Typical Offset Performance

CMRR performance for the range of  $V_{SS} + 1V$  to  $V_{DD} - 1V$  is better than specified in the data sheet.


##### Work around

See [Figure 6](#) and [Figure 7](#).

##### Affected Silicon Revisions


B2	B4						
X							

**FIGURE 6: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE (CxSP = 1),  $V_{DD} = 5.5V$ , PIC16F1782/1783 ONLY**



# PIC16(L)F1782/1783

**FIGURE 7: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE (CxSP = 1), VDD = 3.2V**



## 4. Module: Data EEPROM

### 4.1 Endurance of the Data EEPROM is 10k

The write/erase endurance of the data EE memory is limited to 10k cycles when VDD < 2.3V. This errata applies to the PIC16LF1782/1783 only.

#### **Work around**

Use an error correction method that stores data in multiple locations.

#### **Affected Silicon Revisions**

B2	B4						
X							

## 5. Module: HF Internal Oscillator

### 5.1 Clock Switching

When switching clock sources between INTOSC clock source and an external clock source, one corrupted instruction may be executed after the switch occurs.

This issue affects Two-Speed Start-up operation.

#### **Work around**

When switching from an external oscillator clock source, first switch to 16 MHz HFINTOSC. Once running at 16 MHz HFINTOSC, configure IRCF to run at desired internal oscillator frequency.

When switching from an internal oscillator (INTOSC) to an external oscillator clock source, first switch to HFINTOSC High-Power mode (8 MHz or 16 MHz). Once running from HFINTOSC, switch to the external oscillator clock source.

#### **Affected Silicon Revisions**

B2	B4						
X							

## 6. Module: PSMC

### 6.1 Rising Edge Inhibit

When the period and falling edge sources are from the same asynchronous input, then a race condition may occur where the period is detected before the falling edge. When this occurs, then the falling edge properly terminates the cycle but subsequent rising edge inputs are ignored.

#### Work around

To configure the PSMC for fixed off-time and variable frequency, set the following:

- Period = Asynchronous feedback
- Rising Event = Synchronous @ PSMCxPH = 0
- Falling Event = Synchronous @ PSMCxDC = Off Time
- Output inverted so drive time is from falling event to period event.

#### Affected Silicon Revisions

B2	B4						
X	X						

### 6.2 Auto-Restart

When auto-shutdown is configured for auto-restart and the shutdown source is a comparator, then auto-restart may fail to occur after the shutdown condition ceases.

#### Work around

Enable the zero-latency filter of the comparator used for auto-shutdown.

#### Affected Silicon Revisions

B2	B4						
X							

## 7. Module: Low-Dropout (LDO) Voltage Regulator

### 7.1 Low-Power Sleep mode at ambient temperatures below 0°C

Under the following conditions:

- ambient temperatures below 0°C
- while in Sleep mode
- VREGCON configured for Low-Power Sleep mode (VREGPM = 1)

On very rare occasions, the LDO voltage will drop below the minimum V<sub>DD</sub>, causing unexpected device Resets.

#### Work around

For applications that operate at ambient temperatures below 0°C, use the LDO voltage regulator in Normal-Power mode (VREGPM = 0).

#### Affected Silicon Revisions

B2	B4						
X	X						

## 8. Module: FVR

### 8.1 FVR Module

When using the FVR module, if the gain amplifier outputs are set via the CDAFVR or ADFVR bits in FVRCON while the module is disabled (FVREN = 0), the internal oscillator frequency may shift, device current consumption can increase, and a Brown-out Reset may occur. Additionally, after the FVREN is enabled, a switch from 4x to 1x can also cause a Reset.

#### Work around

Set the FVREN bit of FVRCON to enable the module prior to adjusting the amplifier output selections with the CDAFVR and ADFVR bits. Always set the amplifier output selections to off ('00') before disabling the FVR module.

When switching from 4x to 1x, first switch from 4x to 2x and then from 2x to 1x.

#### Affected Silicon Revisions

B2	B4						
X	X						

## 9. Module: PFM Self-Writes

### 9.1 PFM

Writes to the PFM will not execute if the device's clock source is HS, ECH, or the Internal oscillator is at either 8 MHz or 16 MHz. The DFM is unaffected.

#### Work around

To write to the PFM, the clock source must be one of the following settings: Internal oscillator set to 4 MHz or lower, ECM, ECL, XT, External RC, LP or T1OSC.

#### Affected Silicon Revisions

B2	B4						
	X						

# PIC16(L)F1782/1783

---

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS41579D):

<p><b>Note:</b> Corrections are shown in <b>bold</b>. Where possible, the original bold text formatting has been removed for clarity.</p>
---

None.

## APPENDIX A: DOCUMENT REVISION HISTORY

### **Rev A Document (03/2012)**

Initial release of this document.

### **Rev B Document (07/2012)**

Added MPLAB X IDE; Added Silicon Revision B4;  
Updated Module 6.1; Added Modules 6.2, 7, 8 and 9.

### **Rev C Document (09/2012)**

Removed Silicon Revision B4 from Module 4, Data  
EEPROM.

### **Rev D Document (05/2014)**

Added Module 1.4; Other minor corrections.

---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.


Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rFLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2012-2014, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-63276-209-2

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
= ISO/TS 16949 =**



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110

**Canada - Toronto**  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hangzhou**  
Tel: 86-571-8792-8115  
Fax: 86-571-8792-8116

**China - Hong Kong SAR**  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8864-2200  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-3019-1500

**Japan - Osaka**  
Tel: 81-6-6152-7160  
Fax: 81-6-6152-9310

**Japan - Tokyo**  
Tel: 81-3-6880-3770  
Fax: 81-3-6880-3771

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-5778-366  
Fax: 886-3-5770-955

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Dusseldorf**  
Tel: 49-2129-3766400

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Pforzheim**  
Tel: 49-7231-424750

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Venice**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Poland - Warsaw**  
Tel: 48-22-3325737

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91



**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820

03/25/14

## Looking for pricing, stock, or lifecycle information?

Click below to explore more details on WIN SOURCE:

-  [View PIC16F1783-I/SS on WIN SOURCE](#)
-  [Microchip Technology](#) Information

## Optimize Your Supply Chain with WIN SOURCE Solutions

-  Global Sourcing Solution
-  Obsolete Management
-  Cost Control Management
-  Shortage Management
-  Alternative Solution
-  Excess Inventory Management