

PIC16(L)F1782/1783 Family Silicon Errata and Data Sheet Clarification

The PIC16(L)F1782/1783 family devices that you have received conform functionally to the current Device Data Sheet (DS41579D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC16(L)F1782/1783 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**B4**).

Data Sheet clarifications and corrections start on page 10, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
 - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon ().
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16(L)F1782/1783 silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	DEVICE ID<13:0> ^{(1),(2)}		
	DEV<8:0>	REV<4:0> Silicon Revision	
		B2	B4
PIC16F1782	01 0111 000	0 0110	0 1000
PIC16LF1782	01 0111 001	0 0110	0 1000
PIC16F1783	01 0110 010	0 0110	0 1000
PIC16LF1783	01 0111 010	0 0110	0 1000

- Note 1:** The Device ID is located in the configuration memory at address 8006h.
- 2:** Refer to the “PIC16(L)F178X Memory Programming Specification” (DS41457) for detailed information on Device and Revision IDs for your specific device.

PIC16(L)F1782/1783

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾	
				B2	B4
ADC	Fosc/2	1.1	Fosc/2 not functional.	X	
ADC	Offset	1.2	Time between conversions affects offset.	X	
ADC	INL (12-bit mode)	1.3	INL is ± 4 LSb.	X	
ADC	FRC	1.4	ADC not functional if using FRC with Fosc < 2 MHz.	X	
Op Amp	Offset	2.1	Offset increases when Common mode < 200 mV.	X	
Comparator	Low-Power mode	3.1	Improper Low-Power mode operation.	X	X
Comparator	Typical Offset Performance mode	3.2	Normal Speed mode.	X	
Data EEPROM	Endurance	4.1	Limited to 10k cycles, VDD < 2.3V, PIC16LF1782/1783.	X	
HF Internal Oscillator	Clock Switching	5.1	Clock switching can cause a single corrupted instruction.	X	
PSMC	Rising Edge Input	6.1	Period and falling edge race condition.	X	X
PSMC	Auto-shutdown	6.2	Failure to auto-restart after shutdown from comparator.	X	
Low-Dropout (LDO) Voltage Regulator	Low-Power Sleep	7.1	Unexpected Resets may occur at ambient temperatures below 0°C.	X	X
FVR	FVR Module	8.1	Use of FVR module can cause device to Reset.	X	X
PFM	PFM Self-Write	9.1	PFM self-write will not work depending on clock selection.		X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**B4**).

1. Module: ADC

1.1 Operation with FOSC/2

The ADC is not functional when the ADCS<2:0> bits of ADCON1 select the Fosc/2 frequency.

Work around

Use the FRC selection which provides a valid TAD time, regardless of the system clock frequency.

Affected Silicon Revisions

B2	B4							
X								

1.2 ADC Offset

The offset error exceeds the data sheet specification when the time between conversions is greater than 100 us.

Work around

The time dependent error is insignificant when the time between conversions is less than 100 us. When the time between conversions is greater than 100 us, take two back-to-back ADC conversions and discard the results of the first conversion.

Affected Silicon Revisions

B2	B4							
X								

PIC16(L)F1782/1783

1.3 ADC INL (12-bit mode)

The ADC linearity is ± 4 LSB for the 12-bit mode. Below are typical INL graphs in 12-bit mode (See [Figure 1](#) and [Figure 2](#)).

Work around

None.

Affected Silicon Revisions

B2	B4						
X							

FIGURE 1: ADC 12-BIT MODE, SINGLE-ENDED INL, $V_{DD} = 3.0V$, $T_{AD} = 4 \mu s$, $25^{\circ}C$, TYPICAL MEASURED VALUES





FIGURE 2: ADC 12-BIT MODE, SINGLE-ENDED INL, $V_{DD} = 5.5V$, $T_{AD} = 4 \mu s$, $25^{\circ}C$, TYPICAL MEASURED VALUES



1.4 Incorrect Readings if using Fosc < 2 MHz

The ADC is not functional if using FRC with Fosc frequencies less than 2 MHz.

Work around

Use frequencies greater than 2 MHz for correct ADC functionality.

Affected Silicon Revisions

B2	B4						
X							

2. Module: Op Amp

2.1 Offset at Low Common Mode

The op amp offset at Common mode input voltages below 200 mV increases with respect to temperature. Below are typical graphs showing the increase in offset (See [Figure 3](#), [Figure 4](#) and [Figure 5](#)).


Work around

None.

Affected Silicon Revisions


B2	B4						
X							

FIGURE 3: OP AMP TYPICAL OFFSET VOLTAGE AT 25°C, HIGH GBWP MODE (OPAxSP = 1), VDD = 3.6V, 0V ≤ CMV ≤ 5.5V




PIC16(L)F1782/1783

**FIGURE 4: OP AMP TYPICAL OFFSET VOLTAGE AT LOW VCM, 85°C,
HIGH GBWP MODE (OPAxSP = 1), V_{DD} = 3.6V, 0V ≤ CMV ≤ 0.5V**



**FIGURE 5: OP AMP TYPICAL OFFSET VOLTAGE AT 85°C,
HIGH GBWP MODE (OPAxSP = 1), V_{DD} = 3.6V, 0.5V ≤ CMV ≤ 3.5V**



3. Module: Comparator

3.1 No Low-Power, No Low-Speed Mode

The comparator operation in Low-Power, Low-Speed mode (CxSP = 0) may not perform properly.

Work around

Use the comparator in High Power mode.

Affected Silicon Revisions

B2	B4						
X	X						

3.2 Typical Offset Performance

CMRR performance for the range of $V_{SS} + 1V$ to $V_{DD} - 1V$ is better than specified in the data sheet.


Work around

See [Figure 6](#) and [Figure 7](#).

Affected Silicon Revisions


B2	B4						
X							

FIGURE 6: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE (CxSP = 1), $V_{DD} = 5.5V$, PIC16F1782/1783 ONLY



PIC16(L)F1782/1783

FIGURE 7: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE (CxSP = 1), VDD = 3.2V



4. Module: Data EEPROM

4.1 Endurance of the Data EEPROM is 10k

The write/erase endurance of the data EE memory is limited to 10k cycles when VDD < 2.3V. This errata applies to the PIC16LF1782/1783 only.

Work around

Use an error correction method that stores data in multiple locations.

Affected Silicon Revisions

B2	B4						
X							

5. Module: HF Internal Oscillator

5.1 Clock Switching

When switching clock sources between INTOSC clock source and an external clock source, one corrupted instruction may be executed after the switch occurs.

This issue affects Two-Speed Start-up operation.

Work around

When switching from an external oscillator clock source, first switch to 16 MHz HFINTOSC. Once running at 16 MHz HFINTOSC, configure IRCF to run at desired internal oscillator frequency.

When switching from an internal oscillator (INTOSC) to an external oscillator clock source, first switch to HFINTOSC High-Power mode (8 MHz or 16 MHz). Once running from HFINTOSC, switch to the external oscillator clock source.

Affected Silicon Revisions

B2	B4						
X							

6. Module: PSMC

6.1 Rising Edge Inhibit

When the period and falling edge sources are from the same asynchronous input, then a race condition may occur where the period is detected before the falling edge. When this occurs, then the falling edge properly terminates the cycle but subsequent rising edge inputs are ignored.

Work around

To configure the PSMC for fixed off-time and variable frequency, set the following:

- Period = Asynchronous feedback
- Rising Event = Synchronous @ PSMCxPH = 0
- Falling Event = Synchronous @ PSMCxDC = Off Time
- Output inverted so drive time is from falling event to period event.

Affected Silicon Revisions

B2	B4						
X	X						

6.2 Auto-Restart

When auto-shutdown is configured for auto-restart and the shutdown source is a comparator, then auto-restart may fail to occur after the shutdown condition ceases.

Work around

Enable the zero-latency filter of the comparator used for auto-shutdown.

Affected Silicon Revisions

B2	B4						
X							

7. Module: Low-Dropout (LDO) Voltage Regulator

7.1 Low-Power Sleep mode at ambient temperatures below 0°C

Under the following conditions:

- ambient temperatures below 0°C
- while in Sleep mode
- VREGCON configured for Low-Power Sleep mode (VREGPM = 1)

On very rare occasions, the LDO voltage will drop below the minimum V_{DD}, causing unexpected device Resets.

Work around

For applications that operate at ambient temperatures below 0°C, use the LDO voltage regulator in Normal-Power mode (VREGPM = 0).

Affected Silicon Revisions

B2	B4						
X	X						

8. Module: FVR

8.1 FVR Module

When using the FVR module, if the gain amplifier outputs are set via the CDAFVR or ADFVR bits in FVRCON while the module is disabled (FVREN = 0), the internal oscillator frequency may shift, device current consumption can increase, and a Brown-out Reset may occur. Additionally, after the FVREN is enabled, a switch from 4x to 1x can also cause a Reset.

Work around

Set the FVREN bit of FVRCON to enable the module prior to adjusting the amplifier output selections with the CDAFVR and ADFVR bits. Always set the amplifier output selections to off ('00') before disabling the FVR module.

When switching from 4x to 1x, first switch from 4x to 2x and then from 2x to 1x.

Affected Silicon Revisions

B2	B4						
X	X						

9. Module: PFM Self-Writes

9.1 PFM

Writes to the PFM will not execute if the device's clock source is HS, ECH, or the Internal oscillator is at either 8 MHz or 16 MHz. The DFM is unaffected.

Work around

To write to the PFM, the clock source must be one of the following settings: Internal oscillator set to 4 MHz or lower, ECM, ECL, XT, External RC, LP or T1OSC.

Affected Silicon Revisions

B2	B4						
	X						

PIC16(L)F1782/1783

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS41579D):

<p>Note: Corrections are shown in bold. Where possible, the original bold text formatting has been removed for clarity.</p>

None.

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (03/2012)

Initial release of this document.

Rev B Document (07/2012)

Added MPLAB X IDE; Added Silicon Revision B4;
Updated Module 6.1; Added Modules 6.2, 7, 8 and 9.

Rev C Document (09/2012)

Removed Silicon Revision B4 from Module 4, Data
EEPROM.

Rev D Document (05/2014)

Added Module 1.4; Other minor corrections.

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.


Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rFLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2012-2014, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-63276-209-2

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
= ISO/TS 16949 =**



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110

Canada - Toronto
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2943-5100
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-8792-8115
Fax: 86-571-8792-8116

China - Hong Kong SAR
Tel: 852-2943-5100
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8864-2200
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-3019-1500

Japan - Osaka
Tel: 81-6-6152-7160
Fax: 81-6-6152-9310

Japan - Tokyo
Tel: 81-3-6880-3770
Fax: 81-3-6880-3771

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Dusseldorf
Tel: 49-2129-3766400

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Pforzheim
Tel: 49-7231-424750

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Venice
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Poland - Warsaw
Tel: 48-22-3325737

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820

03/25/14

Looking for pricing, stock, or lifecycle information?

Click below to explore more details on WIN SOURCE:

 [View PIC16LF1783-I/SO on WIN SOURCE](#)

 [Microchip Technology](#) Information

Optimize Your Supply Chain with WIN SOURCE Solutions

-  Global Sourcing Solution
-  Obsolete Management
-  Cost Control Management
-  Shortage Management
-  Alternative Solution
-  Excess Inventory Management