



PIC18F97J60 Family Rev. A0 Silicon Errata

The PIC18F97J60 family parts you have received conform functionally to the Device Data Sheet (DS39762D), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F97J60 family will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

The following silicon errata apply only to PIC18F97J60 family devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F66J60	0001 1000 000	00000
PIC18F66J65	0001 1111 000	00000
PIC18F67J60	0001 1111 001	00000
PIC18F86J60	0001 1000 001	00000
PIC18F86J65	0001 1111 010	00000
PIC18F87J60	0001 1111 011	00000
PIC18F96J60	0001 1000 010	00000
PIC18F96J65	0001 1111 100	00000
PIC18F97J60	0001 1111 101	00000

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFFh in the device's configuration space. They are shown in binary in the format "DEVID2 DEVID1".

1. Module: Resets

MCLR and BOR Resets behave as a POR Reset. Special Function Registers' Reset values after a MCLR or BOR would have the same values as those after a POR. All other Resets behave as described in the data sheet.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

2. Module: I/O (PORTJ)

Note: This issue is only applicable to the 100-pin device.

When configured to operate in Microcontroller mode (CONFIG3L<EMB1:0> = 11), PORTJ pins do not go to a high-impedance state immediately after a POR Reset. Instead, PORTJ<4,0> are driven low, while all other PORTJ pins are driven high, until the device exits the Reset condition (refer to **Section 4.5.1 "Time-out Sequence"** of the Device Data Sheet for details on when device exits Reset condition) before transitioning to a high-impedance state. Note that since MCLR and BOR Resets are also treated as a POR Reset (see errata issue #1), PORTJ pins will also be driven as outputs until the device exits these Reset conditions.

Work around

If using a PORTJ pin as an input, make sure to check that your circuit will not create a short-circuit condition during a Reset. For example, if you need to have a direct pull-down to ground input, do this on PORTJ<4> or PORTJ<0>, since they are temporary driven low. If using a PORTJ pin as an output, then use a pin that will temporarily drive low for driving active-high loads, and use a pin that temporarily will drive high for driving active-low loads. This way, the temporary output signals are in the Idle state.

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F97J60 FAMILY

3. Module: I/O (PORTJ) and External Memory Bus

Note: This issue is only applicable to the 100-pin device.

In an Extended Microcontroller mode (CONFIG3L<EMB1:0> = 00, 01 or 10), each control signal on PORTJ is supposed to be driven to its Idle state. However, the control signals on PORTJ pins go to a high-impedance state for a brief interval after a MCLR Reset. The brief loss of control signals may cause the corruption of data in memory devices connected to the External Memory Bus (EMB).

Work around

To maintain the default states on the control lines, use pull-up or pull-down resistors on all PORTJ pins (pull-down on PORTJ<4,0>, pull-up on all others).

Date Codes that pertain to this issue:

All engineering and production devices.

4. Module: Ethernet (Buffer Memory)

The receive hardware may corrupt the circular receive buffer (including the Next Packet Pointer and receive status vector fields) when an even value is programmed into the ERXRDPH:ERXRDPTL registers.

Work around

Ensure that only odd addresses are written to the ERXRDPT registers. Assuming that ERXND contains an odd value, many applications can derive a suitable value to write to ERXRDPT by subtracting 1 from the Next Packet Pointer (a value always ensured to be even because of hardware padding) and then compensating for a potential ERXST to ERXND wraparound.

Assuming that the receive buffer area does not span the 1FFFh to 0000h memory boundary, the logic in Example 1 will ensure that ERXRDPT is programmed with an odd value.

EXAMPLE 1:

```
if (Next Packet Pointer - 1 < ERXST) or
   (Next Packet Pointer - 1 > ERXND)
  then:
    ERXRDPT = ERXND
  else:
    ERXRDPT = Next Packet Pointer - 1
```

Date Codes that pertain to this issue:

All engineering and production devices.

5. Module: Ethernet (MIIM)

When writing to any PHY register through the MIIM interface's MIWRL and MIWRH registers, the low byte actually written to the PHY register may be corrupted. The corruption occurs when the following actions are taken:

- The application writes to MIWRL
- The PIC[®] MCU core executes any instruction that reads or writes to any memory address that has the Least Significant six address bits of 36h (``b110110`)
- The application writes to MIWRH

For example, the following sequence will result in a corrupted write to a PHY register:

MOVFF	0xCF5,	MIWRL
NOB		
MOVFF	0xCF6,	MIWRH

In this example, 0xCF5 and 0xCF6 are GPR memory locations that the application wishes to write to the current PHY register defined by the MIREGADR SFR. When the PIC MCU core reads from the GPR at address 0xCF6 (``b110011110110`), the value originally written to MIWRL will be corrupted.

Work around 1

Ensure that following a write to MIWRL, the firmware does not access any of the problem memory locations prior to writing to MIWRH. After finished writing to MIWRH, normal operation can resume.

If interrupts are enabled, disable them prior to writing to MIWRL and MIWRH to prevent an Interrupt Service Routine (ISR) from performing any reads or writes to a problem memory address.

Special care must be taken to ensure that the source data to be written to MIWRH does not result in a problem memory access.

The following PHY write sequence avoids the problem:

1. Copy the low byte, to be written to the PHY, into the PRODL register.
PRODL is at address FF3h and not subject to the memory address issue.
2. Copy the high byte, to be written to the PHY, into the PRODH register.
PRODH is at address FF4h and not subject to the memory address issue.
3. Disable all interrupts by clearing GIEH and GIEL in the INTCON register.
4. Move PRODL into MIWRL.
5. Wait one instruction cycle, as required by the MAC host interface logic.
6. Move PRODH into MIWRH.
7. Enable all interrupts that are needed by restoring GIEH and GIEL in INTCON.

Work around 2

If you cannot disable interrupts, as specified in **Work around 1**, because the application cannot tolerate interrupt latency variations:

- Perform the write (with interrupts enabled), but
- Verify the correct values were written by reading the PHY register

If a corrupted value was written due to an interrupt occurring, perform the write again and reverify. The source data must be stored in a non-problem location.

The application should follow the following procedure:

1. Copy the low byte, to be written to the PHY, into the PRODL register.
PRODL is at address FF3h and not subject to the memory address issue.
2. Copy the high byte, to be written to the PHY, into the PRODH register.
PRODH is at address FF4h and not subject to the memory address issue.
3. Move PRODL into MIWRL.
4. Wait one instruction cycle, as required by the MAC host interface logic.
5. Move PRODH into MIWRH.
6. Wait two Tcy and then poll the BUSY bit (MISTAT<0>) until it is clear.
7. Perform a PHY register read of the same location.
8. Compare the read result with the original value copied to the PRODH:PRODL registers. If they do not match, return to step 1.

Date Codes that pertain to this issue:

All engineering and production devices.

6. Module: Ethernet (RX Filter)

When enabled, the Pattern Match receive filter may allow some packets with an incorrect data pattern to be received. Also, in certain configurations, packets with a valid pattern may be incorrectly discarded.

Work around

Do not use the Pattern Match hardware filter. Instead, use the Unicast, Multicast, Broadcast and Hash Table receive filters to accept all needed packets and filter out unwanted ones in software.

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F97J60 FAMILY

7. Module: Ethernet (TX)

When configured for half duplex and a transmit operation encounters unusual collision timing, there is a small chance that the Ethernet transmit engine will internally deadlock. The PHY will stop transmitting the packet and normal RX operations will continue. However, the TXRTS bit (ECON1<3>) will stay set indefinitely. The TXIF (EIR<3>) and TXERIF (EIR<1>) bits will not become set.

This deadlock condition applies only to half-duplex operation and is most readily observable when the network has a duplex mismatch (i.e., PIC18F97J60 family device is configured for half duplex and the remote node is configured for full duplex). In most cases, high network utilization is needed to observe the issue.

Work around

To prevent most transmit deadlock conditions, issue a TX Logic Reset prior to transmitting each packet:

1. Set TXRST (ECON1<7>)
2. Clear TXRST
3. Wait 1.6 μ s or longer
4. Set TXRTS to start the transmission.

Issuing a TX Logic Reset may cause the Ethernet transmit error interrupt to occur and the associated TXERIF bit to become set, which can be ignored.

To detect and recover from any possible deadlock conditions, applications should implement a timer to poll the TXRTS bit. If the Ethernet hardware enters the deadlock state and fails to clear this bit by the time the timer expires, software should manually clear the TXRTS bit, issue a TX Logic Reset and then set the TXRTS bit to retry transmission. The timer should be cleared and restarted whenever the application sets TXRTS. The timer expiration time should be chosen to allow adequate time for ordinary packets to finish transmitting, after accounting for possible delays due to the medium being occupied by other nodes. For example, a time-out value of 3 ms is suitable since it will allow a maximum length 1518-byte packet to be transmitted at 10Base-T speeds while giving reasonable margin to account for potential collisions.

Date Codes that pertain to this issue:

All engineering and production devices.

8. Module: Ethernet (DMA)

When the DMA is configured to compute an IP checksum, there is a small chance that an incoming packet receive event will cause the DMA to internally deadlock. In these cases, the DMAST bit (ECON1<5>) stays set indefinitely, and the DMA done interrupt never occurs.

Work around

Perform checksum calculations in software. Use the DMA only for copy operations.

Date Codes that pertain to this issue:

All engineering and production devices.

9. Module: I/O (PORTJ)

Note: This issue is only applicable to the 80-pin device.
--

The weak internal pull-up resistors on pins RJ4 and RJ5 cannot be enabled on the PIC18F86J60, PIC18F86J65 and PIC18F87J60 devices. Setting the RJPU bit (PORTA<7>) has no effect on the I/O pin state.

Work around

Install external pull-up resistors on RJ4 and RJ5. Alternatively, use any of the PORTB, PORTD or PORTE pins which all have weak internal pull ups.

Date Codes that pertain to this issue:

All engineering and production devices.

REVISION HISTORY

Rev A Document (9/2006)

Original version of this document. Includes silicon issues 1 (Resets), 2 (I/O – PORTJ), 3 (I/O (PORTJ) and External Memory Bus), 4 (Ethernet – Buffer Memory) and 5 (Ethernet – PHY).

Rev B Document (2/2007)

Modified issue 5 (Ethernet – PHY) and added issue 6 (Ethernet – Buffer Memory).

Rev C Document (6/2007)

Removed previous silicon issues 5 (Ethernet – PHY) and 6 (Ethernet – Buffer Memory). Added new silicon issues 5 (Ethernet – MIIM) and 6 (Ethernet – RX Filter).

Rev D Document (6/2008)

Added new silicon issues 7 (Ethernet – TX), 8 (Ethernet – DMA) and 9 (I/O – PORTJ).

PIC18F97J60 FAMILY

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

Looking for pricing, stock, or lifecycle information?

Click below to explore more details on WIN SOURCE:

- ⊖ [View PIC18F86J60-I/PT on WIN SOURCE](#)
- ⊖ [Microchip Technology Information](#)

Optimize Your Supply Chain with WIN SOURCE Solutions

- ✓ Global Sourcing Solution
- ✓ Obsolete Management
- ✓ Cost Control Management
- ✓ Shortage Management
- ✓ Alternative Solution
- ✓ Excess Inventory Management