





\*SLIGHT PROTRUSIONS  
MAY APPEAR ON PARTS

TO SNAP-LOCK IN A .118±.002  
[3.0±0.05] HOLE DIA. IN A  
PANEL THICKNESS INDICATED

NYLON 6/6 (RMS-01) COLOR: NATURAL PART NO.	FLAME RETARDANT NYLON 6/6 (RMS-19) COLOR: NATURAL PART NO.	"A" REF.	"B" REF.	"C"
*MWSEA1-1-01	*MWSEA1-1-19	.29 (7.3)	.12 (3.0)	.36
MWSEA1-2-01	MWSEA1-2-19	.36 (9.1)	.16 (3.9)	.42
MWSEA1-3-01	MWSEA1-3-19	.44 (11.2)	.24 (6.0)	.47
MWSEA1-4-01	MWSEA1-4-19	.51 (13.0)	.30 (7.7)	.47
*MWSEA1-1-1-01	*MWSEA1-1-1-19	.29 (7.3)	.12 (3.0)	.36
MWSEA1-1-2-01	MWSEA1-1-2-19	.36 (9.1)	.16 (3.9)	.42
MWSEA1-1-3-01	MWSEA1-1-3-19	.44 (11.2)	.24 (6.0)	.47
MWSEA1-1-4-01	MWSEA1-1-4-19	.51 (13.0)	.30 (7.7)	.47

TITLE:

## MICRO WIRE SADDLE

E	SEE CO 200190 FOR CHANGES	S.K.	05/22/08
D	COMPLETELY REDRAWN, SEE EGN #709	S.M.	10.06.03
C	UPDATED TABLE, AND ADDED .093 [2.36] PANEL THK. P/N FOR RMS-19 ADDED TO TABLE	S.M.	05.01.02
B		J.L.	08.08.00
A	PART # CHART ADDED, DIM [4.0] WAS [4.3]	J.L.	03.06.98
REV.	DESCRIPTION	ENGR.	DATE

CREATED BY:  
SOLIDWORKS

FILE #: MWSEA1

DWN: SM

APP: -

TOLERANCES  
UNLESS NOTED

SHEET: 1 OF 1

DT: 10/06/03

CHKD: -

.XX±.010

RE: RICHCO, INC.

**RICHCO, INC.**

.XXX±.005

ENG@RICHCO-INC.COM

FRAC = ±1/64

(773) 539-4060

ANG = ±1°

## Looking for pricing, stock, or lifecycle information?

Click below to explore more details on WIN SOURCE:

- ⊖ [View MWSEA1-3-01](#) on WIN SOURCE
- ⊖ [Essentra Components](#) Information

## Optimize Your Supply Chain with WIN SOURCE Solutions

- ✓ Global Sourcing Solution
- ✓ Obsolete Management
- ✓ Cost Control Management
- ✓ Shortage Management
- ✓ Alternative Solution
- ✓ Excess Inventory Management