



**THE DATASHEET OF
LC706161CM**





FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20095

Generic Copy

Issue Date: 30-May-2013

TITLE: (CHIP) Production assembly process will be transferred from SANYO-HANYU site to SSMP

PROPOSED FIRST SHIP DATE: 6-Sep-2013

AFFECTED CHANGE CATEGORY(S): Assembly site

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Takehito.Tsukui@onsemi.com

SAMPLES: Contact your local ON Semiconductor Sales Office

ADDITIONAL RELIABILITY DATA: No Need Assembly Only

NOTIFICATION TYPE:

Final Product/Process Change Notification (FPCN)

Final change notification sent to customers. FPCNs are issued at least 90 days prior to implementation of the change.

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

Production assembly process will be transferred from SANYO-HANYU (CHIP) site to SSMP (Sanyo Semiconductor Manufacturing Philippines Corporation).

There will be no other changes that include the electrical characteristics specification other than mentioned above.



FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20095

RELIABILITY DATA SUMMARY: N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

There are not any other changes including electric characteristic specifications.

CHANGED PART IDENTIFICATION:

Products manufactured at SSMP will be marked with 'L7' preceding the Lot No. on shipping label.

List of affected General Parts:

LC70615C-4-W1

LC706161CM

LC706171CM

Looking for pricing, stock, or lifecycle information?

Click below to explore more details on WIN SOURCE:

- ⊖ [View LC706161CM](#) on WIN SOURCE
- ⊖ [ON Semiconductor](#) Information

Optimize Your Supply Chain with WIN SOURCE Solutions

- ✓ Global Sourcing Solution
- ✓ Obsolete Management
- ✓ Cost Control Management
- ✓ Shortage Management
- ✓ Alternative Solution
- ✓ Excess Inventory Management